



SURFACE PREPARATION PRODUCTS

CASE HISTORY

VpCI® CorVerter™ /VpCI®-368/VpCI®-386/VpCI®-426/VpCI®-705/Rawn Engine Degreaser/Bullfrog Fast Wax

DATE

September 2001

CUSTOMER

Cortec® Advanced Films Division

PROBLEM

Cortec® Advanced Films division owned a truck that needed protection. Due to the harsh climate of central Minnesota, and the extreme amount of deicing compounds used on the road, portions of the truck had corroded considerably.



SOLUTION AND APPLICATION

A team of Cortec® employees were asked to rehabilitate the truck and enhance its appearance. The areas in need of attention were the chrome wheel wells, the fifth wheel attachment/ under carriage, the engine compartment, and the overall visual exterior of the truck.

Using VpCI®-426 to remove corrosion on the vehicle and Bullfrog fast wax for short-term protection the wheels and body of the vehicle were restored to an almost new state. Rawn engine degreaser cleaned the engine, and the undercarriage was coated with VpCI®-386. The fifth wheel attachment and under carriage was then coated with VpCI® CorVerter™ and VpCI®-386 to give an attractive and resilient finish that will prohibit corrosion for years to come.

CONCLUSION

The truck was transformed from an average 3-year-old truck to a lustrous, corrosion free and protected vehicle. This application will add to the resale value and extend the service life of the equipment.